

Oil Field Environmental Incident Summary

Incident: 20140717085246 **Date/Time of Notice:** 07/17/2014 08:52

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BB-STATE-151-96- 3625H-1

Field Name: BLUE BUTTES

Well File #: 18053

Date Incident: 7/15/2014

Time Incident: 13:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 96

Sec: 36

Qtr:

Location Description:

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	18	Barrels			5	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/27/2015

Clean Up Concluded: 8/15/2014

Risk Evaluation:

N/A - The release was contained in the secondary containment berm around the tank.

Areal Extent:

The release was contained in the secondary containment berm around the tank.

Potential Environmental Impacts:

The release occurred above ground and was confined to the secondary containment berm around the tank.

Action Taken or Planned:

The fitting on the tank will be repaired/replaced, and a vacuum truck will be dispatched to recover the produced water from the secondary containment berm.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

Updates

Date: 7/17/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.